

MP20 Firmware Release Notes

Release Date: 2024.4.30
MP20 Firmware Version: MP20_V01.01.01.00

Supported Products and Firmware Version:

DJI Dock 2

Airport firmware: V09.02.0108


Aircraft firmware: V09.02.0108

Remote control firmware: V02.01.0322

DJI Pilot 2 App: V9.2.0.26

更新了什么?

1. Fixed popping sound issue during playback.
2. Fixed inconsistent volume display issue.
3. Fixed the issue of no sound during the first playback of a recording.
4. Optimized PSDK connection speed.
5. Added automatic sound mute within 10 meters of landing after airport takeoff.
6. Fixed PSDK disconnection issue after deleting songs.
7. Updated broadcast voice and added a broadcast for connecting to the host computer.
8. Added a floating window to display volume, avoiding the issue of volume adjustment failure in Sikong 2.
9. Fixed the issue where the floating window is not displayed after uploading audio or recording in Sikong 2.




MP20 Firmware Release Notes

Release Date: 2023.12.15
MP20 Firmware Version: MP20_V01.00.00.26

Supported Products and Firmware Version:

What has been updated?

1. Fixed the issue where the last song could not be deleted.
2. Added TTS character limit of approximately 440 characters, resolving the problem of abnormal playback with long texts.
3. Implemented media status monitoring, automatically restarting media after playback issues to resolve the problem of requiring a restart to function properly.
4. Optimized version announcement.



Fix the issue

1. Long text playback for English, French, Italian, Russian, Latvian, Spanish, and other languages is incomplete.
2. If the playback is not normal on the first attempt, subsequent playback of other TTS also fails to play properly, requiring a restart to enable normal TTS playback.