

LP20 Firmware Release Notes

Release Date: 2024.12.31
LP20 Firmware Version: LP20_V02.00.02.08

Supported Products and Firmware Version:

Czi Assistant: V1.0.45

DJI Dock 2


Airport firmware: V10.01.32.05

Aircraft firmware: V02.01.05.17

DJI Pilot 2 App: V10.1.8.17

What has been updated?

1. Updated PSDK version V3.9.2-2125.
2. Repair failure of alarm searchlight function due to frequent operation.



Notice

1. Only when the searchlight is turned on, it will follow the camera movement; If it is not enabled, it will not follow.
2. When the latest airport firmware V10.01.32.05 is used for flight test, the speed limit will be 1-2m per second during ascent (normal with the old firmware V10.01.16.07).
3. Cheng to assistant renamed special symbol (@#¥!)The audio cannot be played properly after being uploaded.

LP20 Firmware Release Notes

Release Date: 2024.11.04
LP20 Firmware Version: LP20_V02.00.02.07

Supported Products and Firmware Version:

Czi Assistant: V1.0.45

DJI Dock 2


Airport firmware: V10.01.32.05

Aircraft firmware: V02.01.05.15

DJI Pilot 2 App: V10.1.8.1

What has been updated?

1. Add TTS language speed saving.
2. Optimize the TTS language sequence.
3. Added the Chinese/English switching function in the suspension window.
4. Optimize searchlight motion logic.



Notice

1. Only when the searchlight is turned on, it will follow the camera movement; If it is not enabled, it will not follow.
2. When the latest airport firmware V10.01.32.05 is used for flight test, the speed limit will be 1-2m per second during ascent (normal with the old firmware V10.01.16.07).
3. Cheng to assistant renamed special symbol (@#¥!)The audio cannot be played properly after being uploaded.