

FL48 Firmware Release Notes

Release Date: 2025.02.21

FL48 Firmware Version: FL48_V03.09.01.01

Supported Products and Firmware Version:

M300 RTK + DJI Smart ControllerEnterprise

Aircraft firmware: V10.01.08.01

Remote control firmware: V10.01.08.01

DJI Pilot 2 App: V10.1.8.14

M350 RTK + DJI RC Plus

Aircraft firmware: V10.01.08.05

Remote control firmware: V05.02.13.02

DJI Pilot 2 App: V10.1.8.18

What has been updated?

1. Fixed an issue where control information was still in Chinese when the system language was switched to English.

Notice

1. At present, M350 can only control the alarm lights through Pilot2.

FL48 Firmware Release Notes

Release Date: 2024.07.29

FL48 Firmware Version: FL48_V03.09.01.00

Supported Products and Firmware Version:

M300 RTK + DJI Smart ControllerEnterprise

Aircraft firmware: V09.00.05.03

Remote control firmware: V09.00.05.01

DJI Pilot 2 App: V9.0.5.5

M300 RTK + DJI RC Plus

Aircraft firmware: V60.01.00.03

Remote control firmware: V05.02.11.06

DJI Pilot 2 App: V10.1.0.30

M350 RTK + DJI RC Plus

Aircraft firmware: V10.01.00.09

Remote control firmware: V05.02.11.06

DJI Pilot 2 App: V10.1.0.30

What has been updated?

1. Based on DJI PSDK 3.9.1_2090, compatible with the latest DJI aircraft firmware.

Notice

1. At present, M350 can only control the alarm lights through Pilot2.

FL48 Firmware Release Notes

Release Date: 2024.01.19
FL48 Firmware Version: FL48_V03.08.00.00

Supported Products and Firmware Version:

M300 RTK + DJI Smart ControllerEnterprise

Aircraft firmware: V09.00.05.03

Remote control firmware: V09.00.05.01

DJI Pilot 2 App: V9.0.5.5

M300 RTK + DJI RC Plus

Aircraft firmware: V58.00.00.10

Remote control firmware: V02.02.08.03

DJI Pilot 2 App: V9.0.5.39

M350 RTK + DJI RC Plus

Aircraft firmware: V09.00.05.03

Remote control firmware: V02.02.08.03

DJI Pilot 2 App: V9.0.5.39

What has been updated?

1. Based on DJI PSDK 3.8.0_1929.

Notice

1. At present, M350 can only control the alarm lights through Pilot2.

FL48 Firmware Release Notes

Release Date: 2023.09.01
FL48 Firmware Version: FL48_V03.03.06.00

Supported Products and Firmware Version:

M300 RTK + DJI Smart ControllerEnterprise

Aircraft firmware: V07.00.01.00

Remote control firmware: V07.00.01.00

DJI Pilot 2 App: V7.0.1.1

M300 RTK + DJI RC Plus

Aircraft firmware: V57.00.00.09

Remote control firmware: V01.02.04.40

DJI Pilot 2 App: V7.0.1.0

M350 RTK + DJI RC Plus

Aircraft firmware: V07.00.00.01

Remote control firmware: V01.02.04.40

DJI Pilot 2 App: V7.0.1.0

What has been updated?

1. Adapted to M350 & M300 new airplane firmware, can be used in both airplane models at the same time, startup time will be a little slower on M300.

Notice

1. At present, M350 can only control the alarm lights through Pilot2.

FL48 Firmware Release Notes

Release Date: 2023.06.06

FL48 Firmware Version: FL48_V03.03.05.00

What has been updated?

1. Based on PSDK350_1765, Adapting latest M350 firmware.

Notice

1. At present, M350 can only control the alarm lights through Pilot2.

FL48 Firmware Release Notes

Release Date: 2023.06.06

FL48 Firmware Version: FL48_V03.03.00.00

What has been updated?

1. Based on PSDK350_1765,Adapting latest M300 firmware.

FL48 Firmware Release Notes

Release Date: 2023.03.21

FL48 Firmware Version: FL48_V03.01.01.22

What has been updated?

1. Based on PSDK330_1705,Adapting latest M300 firmware.

FL48 Firmware Release Notes

Release Date: 2023.03.03

FL48 Firmware Version: FL48_V03.01.01.21

What has been updated?

1. Based on PSDK320_1539.
2. Enable PILOT2 control function.
3. The baud rate for communication between the control box and the drone has been revised to 115200.

Fix the issue

1. Fix the bug that the floating window component of czi assistant cannot control the alarm light switch properly.

FL48 Firmware Release Notes

Release Date: 2022.12.27
FL48 Firmware Version: FL48_V03.01.01.19

What has been updated?

1. Based on PSDK330_1659, adapt with DJI M30 series Drone' s firmware version V05.01.00.00.
2. Enable PILOT2 control function.
3. The baud rate for communication between the control box and the drone has been revised to 115,200.

Known Issues

1. CZZN floating window' s switch lights function occasionally out of control. Will fix it next firmware upgrade.

FL48 Firmware Release Notes

Release Date: 2022.05.11
FL48 Firmware Version: FL48_V03.01.00.00

What has been updated?

1. Adapt to the incoming new firmware of M300 plane and PILOT2 app on monitor.