

## **FL48 版本 03.01.01.19:**

### **新功能:**

1. 移植 PSDK320\_1539, 适配大疆 M300 飞行器 V05.01.01.00 版本固件
2. 开启 PILOT2 控制功能
3. 控制盒与飞行器通信的波特率修改为 115200

**已知问题:** czzn 浮窗控制开关灯偶尔失控, 待修复

## **FL48 Firmware Version - 03.01.01.19:**

### **New Features:**

1. Based on PSDK330\_1659, adapt with DJI M30 series Drone's firmware version V05.01.00.00.
2. Enable PILOT2 control function.
3. The baud rate for communication between the control box and the drone has been revised to 115,200.

**Current issue:** CZZN floating window's switch lights function occasionally out of control. Will fix it next firmware upgrade.