

PK10 Firmware Release Notes

Release Date: 2023.12.26
PK10 Firmware Version: CPUE_01.01.06.00

Supported Products and Firmware Version:

DJI Mavic 3E+DJI RC Pro

Aircraft firmware: V07.01.20.01


Remote control firmware: V02.01.01.08

CZI Pilot software: V1.2.2

Zhisheng app version (Android) : V1.3.0_RC2

What has been updated?

1. Auto-repair feature for empty configuration information.
2. Implementation of configuration information backup and storage to NVS partition.



Known Issues

1. When enabling monitoring, playing a video recording or audio file may result in the simultaneous playback of two audio tracks.
2. During the live broadcast, when the monitoring button is turned off, the screen may freeze. Normal playback is restored upon reactivating monitoring.
3. The upgrade pop-up has not disappeared after a successful offline upgrade.
4. When starting the live stream without enabling monitoring, the audio will be 2 seconds ahead of the video after successfully starting the live stream.
5. Turning off monitoring, streaming still has (bitrate and network speed) data, but the live broadcast screen is black.
6. In photo mode, the picture may stretch.
7. During usage, when switching from DJI to CZI, CZI cannot detect the load.

PK10 Firmware Release Notes

Release Date: 2023.11.24
PK10 Firmware Version: CPUE_01.01.05.02

Supported Products and Firmware Version:

DJI Mavic 3E+DJI RC Pro

Aircraft firmware: V07.01.20.01


Remote control firmware: V02.01.00.07

CZI Pilot software: V1.2.2

Zhisheng app version (Android) : V1.1.0

What has been updated?

1. Add Firmware Version&Language Type Setting Command.
2. Optimization of the log printing when the aircraft is not connected.
3. Optimization of the automatic device restart when the aircraft is not connected.



Known Issues

1. When enabling monitoring, playing a video recording or audio file may result in the simultaneous playback of two audio tracks.
2. During the live broadcast, when the monitoring button is turned off, the screen may freeze. Normal playback is restored upon reactivating monitoring.
3. The upgrade pop-up has not disappeared after a successful offline upgrade.
4. When starting the live stream without enabling monitoring, the audio will be 2 seconds ahead of the video after successfully starting the live stream.

PK10 Firmware Release Notes

Release Date: 2023.11.17
PK10 Firmware Version: CPUE_01.01.05.01

Supported Products and Firmware Version:

DJI Mavic 3E+DJI RC Pro

Aircraft firmware: V07.01.20.01


Remote control firmware: V02.01.00.07

CZI Pilot software: V1.2.2

Zhisheng app version (Android): V1.1.0

What has been updated?

1.By default, the production demand assumes that the device is already activated, and quality inspection at the factory will clear the device activation.



Known Issues

- 1.When enabling monitoring, playing a video recording or audio file may result in the simultaneous playback of two audio tracks.
- 2.During the live broadcast, when the monitoring button is turned off, the screen may freeze. Normal playback is restored upon reactivating monitoring.
- 3.The upgrade pop-up has not disappeared after a successful offline upgrade.