

C30N Firmware release record

Release date :	2023.07.05
C30N Payload:	V02.03.21.25
	DJI Skyport V2: V01.03.05.00
	CZI Pilot: V01.02
	M300 RTK + DJI Smart Controller Enterprise
	Aircraft Firmware: V07.00.01.00
	Remote Controller Firmware: V07.00.01.00
	DJI Pilot 2 App: V7.0.1.1
Compatible Firmware and Software Required:	M300 RTK + DJI RC Plus
	Aircraft Firmware: V57.00.01.00
	Remote Controller Firmware: V01.02.04.40
	DJI Pilot 2 App: V7.0.1.0
	M350 RTK + DJI RC Plus
	Aircraft Firmware: V07.00.00.01
	Remote Controller Firmware: V01.02.04.40
	DJI Pilot 2 App: V7.0.1.0

What has been updated?

- Optimized the intelligent tracking function
- Added infrared detection capability
- Optimized the accuracy of the gimbal
- Fixed some known issues

Notice

- Ensure that the CZI Pilot App, C30N firmware, aircraft, remote control, DJI Skyport V2 firmware, and DJI Pilot 2 App are updated to the latest version, otherwise it will affect use.
- Restart the camera after the upgrade is complete.

C30N Firmware release record

Release date:	2023.05.16
C30N Payload:	V02.02.11.13

What has been updated?

- Optimize visible light night effect optimization
- New mountain fire mode for thermal imaging cameras
- New thermal imaging camera for probabilistic temperature measurement
- The addition of a QR code sharing function for ranging and pointing coordinates
- Optimize the head control, increase the automatic calibration function of the head
- Add image exif information
- Newly added light ground safety restrictions

Notice

- Be sure to update both the CZI Pilot App and the C30N firmware to the latest version, otherwise it will not work.