

Firmware Version

Attention: Please update the latest drone firmware as well to use the firmware.

V02.06.02.00:

Gimbal optimize

V02.06.01.00:

Gimbal optimize;

Fix the error could've happened while restoreFactory

V02.04.01.00:

Update with latest M3 plane firmware;

Function to connect to CziAssistant Software(release later);

Optimize log issue

V02.02.07.00:

Optimize activation, need no manual reboot after activate;

Gimbal optimize

V02.02.02.04:

Fix that pilot software could not detect activation error;

Gimbal optimize

V02.02.02.01:

Optimize kinds of problems

V02.02.01.01:

Fix the problem that PILOT software quits under certain circumstances;

Optimize gimbal function

V02.02.00.00:

Optimize AI function speed;

Adapted to the latest drone firmware

V02.01.00.00:

Adapt the latest drone firmware;

Adapted the usage and activation of CZI_PILOT;

Add single mode select for alamp flash light;

Update window message show;

Payload Status Light update.